
Docket No.: HO-P02832US0

App No.: Not Yet Assigned Docket No.: HO-P02i Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE WARNING SYSTEM





App No.: Not Yet Assigned Docket No.: HO-P02 Inventor: Mark K. Hennig, et al. Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE WARNING SYSTEM Docket No.: HO-P02832US0




FIG. 2

Docket No.: HO-P02832US0

App No.: Not Yet Assigned Docket No.: HO-P02
Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE
WARNING SYSTEM




FIG. 3

App No.: Not Yet Assigned Docket No.: HO-P02 Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE WARNING SYSTEM

Docket No.: HO-P02832US0




FIG. 4

App No.: Not Yet Assigned Docket No.: HO-P02 Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE WARNING SYSTEM Docket No.: HO-P02832US0




FIG. 5

App No.: Not Yet Assigned Docket No.: HO-P02
Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE
WARNING SYSTEM

Docket No.: HO-P02832US0






FIG. 6



App No.: Not Yet Assigned Docket No.: HO-P02 Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE WARNING SYSTEM

Docket No.: HO-P02832US0



App No.: Not Yet Assigned Docket No.: HO-P02 Inventor: Mark K. Hennig, et al.
Title: WHEEL END ASSEMBLY HIGH-TEMPERATURE WARNING SYSTEM



Docket No.: HO-P02832US0

